

# TURBOCHARGERS

## HIGHLY FAILURE PRONE ORIGINAL PART

### Comprehensive Coverage


Over 30 SKUs, Covering More Than 6 Million Vehicle Applications

Installation components included for a complete repair



**667-203**


Buick 2017-13, Chevrolet 2017-11



- Replacement eliminates grinding, whining or other noise-related issues due to a faulty turbocharger
- Undergoes on-vehicle, salt spray (for corrosion) and balance testing to ensure long lasting quality

#### FAILURE MODE:

- Damaged turbocharger blade caused by contamination from dirt or other particles entering the turbine or compressor housing



### ALSO AVAILABLE

**917-152**

Mazda 3 2013-07, Mazda 6 2007-06


### OTHER TURBOCHARGER PARTS AVAILABLE



#### Turbocharger Cartridges

**667-001**

Dorman enables technicians to replace just the worn original turbo cartridge versus the complete assembly



#### Boost Solenoids

**667-106**

Over 5 SKUs available, covering more than 3.3 million VIO



#### Intercooler Boots and Hose Kits

**904-272**

Upgrades the original from plastic to a metal design for a longer service life



#### Turbocharger Feed and Return Lines

**904-137**

Over 20 SKUs available, covering more than 7.3 million VIO



#### V-Band Exhaust Clamps

**904-250**

Over 10 SKUs, covering more than 9 million VIO

Think It's Dealer Only? **Check Dorman First!**

