

POWER WINDOW MOTOR AND REGULATOR ASSEMBLY

LINE EXTENSION

AFTERMARKET LEADING COVERAGE & QUALITY

Over 2,400 Part Numbers Covering Over 200 Million VIO







OE PROBLEM:

Original units fail when cable pulls free from broken plastic window slide.



Improved design includes metal cable grips and over molded window slide for added strength.




Power Window Motor and Regulator Assembly

Mechanical component attached to window glass enabling the ability to raise and lower vehicle window


748-568: Jeep Liberty 2007-02

Failure Mode:

· Wear of mechanical pieces, rust and corrosion



741-306 [FL], **741-307** [FR]: Honda Accord 2007-03



748-524 [FL], 748-525 [FR]: Infiniti QX56 2010-04, Nissan Armada 2013-05, Pathfinder 2004, Titan 2010-04



748-576 [FR], 748-577 [FL]:Jeep Liberty 2012-08





POWER WINDOW MOTOR AND REGULATOR ASSEMBLY

LINE EXTENSION



Our **Quality**

We know Techs demand quality products. At Dorman, we design and quality test our Window Regulators to provide exceptional performance, durability and a trouble free installation.

Our Coverage

We know Techs cannot afford to wait on parts. Dorman leads the market with more than 2,400 Window Regulators, providing comprehensive coverage for over 200 million vehicles.





Our Innovation

Dorman's engineering abilities help keep Technicians up-to-date with today's complex window motor designs. Advanced capabilities such as printed circuit integration and embedded software engineering drive industry leading Window Regulator innovation you can trust.

Our Solutions

We know Techs value solutions to common OE problems. Dorman's commitment to engineering solutions, quality focus, advanced technology and market leading coverage makes us the trusted choice for Window Regulators.



For complete Power Window Motor and Regulator Assembly coverage, visit DormanProducts.com

NEW PRODUCTS • NEW OPPORTUNITIES • NEW SOLUTIONS



DOR75969-2

